

LED420-series



TECHNICAL DATA

Visible LED InGaN

LED420-series are InGaN LEDs mounted on a lead frame and encapsulated in various types of clear silicone lens, which offers different design settings.

On forward bias, it emits a radiation of typical 15 mW at a peak wavelength at 420 nm.

Specifications

Structure: InGaN

Peak Wavelength: typ. 420 nm
Optical Ouput Power: typ. 15 mW
Resin Material: Clear silicone resin

Solder: Lead free



Absolute Maximum Ratings (T_a=25°C)

Туре	Symbol	Value	Unit
Power Dissipation	P_{D}	200	mW
Forward Current	I _F	50	mA
Reverse Voltage	V_R	5	V
Operating Temperature	T _{OP}	-30 +85	°C
Storage Temperature	T _{STG}	-40 +100	°C
Soldering Temperature (for 5 sec.)	T _{SOL}	265	°C

Electro-Optical Characteristics (T_a=25°C)

Item	Symbol	Condition	Min.	Тур.	Max.	Unit
Forward Voltage	V_{F}	$I_F = 20 \text{ mA}$	-	3.4	4.0	V
Reverse Current	I_R	$V_R = 5 V$	-	-	10	μA
Radiated Power	Po	$I_F = 20 \text{ mA}$	-	15	-	mW
Peak Wavelength	λ_{P}	$I_F = 20 \text{ mA}$	415	420	425	nm
Half Width	Δλ	$I_F = 20 \text{ mA}$	-	15	1	nm







Characteristics of Radiant Intensity (T_a =25°C)


WIEDNER HAUPTSTRASSE 76

Туре	Viewing Half Angle	Brightness / Radiation Intensity (I _F = 20 mA) [Unit: mW/sr]			Outer Dimension	Dimension Figure
		Min.	Тур.	Max.		
LED420-01	±8°		60		Ø 5	1
LED420-02	±5°		60		Ø 5	2
LED420-03	±10°		40		Ø 5	3
LED420-04	±20°		12		Ø 5	4
LED420-05	±50°		4		Ø 5	5
LED420-06	±4°		90		Ø5	6
LED400.00	±25° (long)				Ø 5	7
LED420-09	±10° (short)				Oval	7
LED420-46					Ø5	8
LED420-41	±14°				Ø 4	9
LED420-42	±20°				Ø 4	10
LED420-31					Ø3	11
LED420-33	±13°		18		Ø3	12
LED420-34					Ø3	13
LED420-36	±25°		9		Ø3	14

^{*} Radiant Power is measured by S3584-08

The above specifications are for reference purpose only and subjected to change without prior notice.

Outer Dimensions




^{*} Radiant Intensity is measured by Ando Optical Multi Meter AQ2140 & AQ2741





WIEDNER HAUPTSTRASSE 76 TEL. +43 I 586 52 43 -0, FAX. -44, OFFICE@ROITHNER-LASER.COM

1040 VIENNA AUSTRIA










Figure-7 Ø 5Mold (Type 09) cup position 1.5max 4.7 ± 0.2 7.7 ± 0.2 21 min. ¶1 typ. Cathode -Anode


2-0.5sq±0.1

























Viewing half angle






WIEDNER HAUPTSTRASSE 76

TEL. +43 I 586 52 43 -0, FAX. -44, OFFICE@ROITHNER-LASER.COM




Typical Performance Curves









1040 VIENNA WIEDNER HAUPTSTRASSE 76 TEL. +43 I 586 52 43 -0, FAX. -44, OFFICE@ROITHNER-LASER.COM






Relative Radiant Intensity – Ambient Temperature




Allowable Forward Current – Ambient Temperature






1040 VIENNA **AUSTRIA** TEL. +43 I 586 52 43 -0, FAX. -44, OFFICE@ROITHNER-LASER.COM





WIEDNER HAUPTSTRASSE 76



Precaution for Use

1. Cautions

DO NOT look directly into the emitted light or look through the optical system. To prevent in adequate exposure of the radiation, wear protective glasses.

2. Lead Forming

- When forming leads, the leads should be bent at a point at least 3 mm from the base of the lead. DO NOT use the base of the leadframe as a fulcrum during lead forming.
- Lead forming should be done before soldering.

wavelength (nm)


- DO NOT apply any bending stress to the base of the lead. The stress to the base may damage the LED's characteristics or it may break the LEDs.
- When mounted the LEDs onto the printed circuit board, the holes on the circuit board should be exactly aligned with the leads of LEDs. If the LEDs are mounted with stress at the leads, it causes deterioration of the lead and it will degrade the LEDs.



WIEDNER HAUPTSTRASSE 76 IO40 VIENNA AUSTRIA TEL. +43 I 586 52 43 -0, FAX. -44, OFFICE@ROITHNER-LASER.COM




Recommended Land Layout (Unit: mm)



3. Soldering Conditions

- Solder the LEDs no closer than 3 mm from the base of the lead.
- DO NOT apply any stress to the lead particularly when heat.
- The LEDs must not be reposition after soldering.
- After soldering the LEDs, the lead should be protected from mechanical shock or vibration until the LEDs return to room temperature.
- When it is necessary to clamp the LEDs to prevent soldering failure, it is important to minimize the mechanical stress on the LEDs.
- Cut the LED leads at room temperature. Cutting the leads at high temperature may cause the failure of the LEDs.



4. Static Electricity

- The LEDs are very sensitive to Static Electricity and surge voltage. So it is recommended that a wrist band or an anti-electrostatic glove be used when handling the LEDs.
- All devices, equipment and machinery must be grounded properly. It is recommended that precautions should be taken against surge voltage to the equipment that mounts the LEDs.